



## Life Safety Survey Summary

\*32 AL surveys reviewed; 1 program received no insufficiencies

IFC	DEFICIENT PRACTICE
315.3.1	Combustible Materials Storage Requirements (1 insufficiency)
405.5	Record Keeping (3 insufficiencies)
605.1	Electrical Abatement (6 insufficiencies)
605.1	Electrical Abatement of Electrical Hazards (5 insufficiencies)
605.4	Multi-plug Adapters (6 insufficiencies)
605.4.1	Electrical- Power Tap Design (3 insufficiencies)
605.5	Electrical- Extension Cords (5 insufficiencies)
703.1.3	Maintenance (5 insufficiencies)
703.2	Opening Protectives (4 insufficiencies) <ul style="list-style-type: none"> <li>• 703.2.3- Door Operation (6 insufficiencies)</li> </ul>
901.6.1	Sprinkler systems—inspections & testing (5 insufficiencies)
906.2	General Requirements: Fire extinguishers (2 insufficiencies)
906.9.1	Extinguishers Weighing 40 Pounds or Less (1 insufficiency)
906.9.3	Floor Clearance (1 insufficiency)
1008.3	Means of Egress (2 insufficiencies)
1010.1.3	Door Opening Force (1 insufficiency)
1010.1.9.5	Unlatching (1 insufficiency)
1031.2	Maintenance Means of Egress (1 insufficiency)
5303.5.4	Securing Compressed Gas Cylinders (1 insufficiency)